



# GARFIELD LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004518	Utility	Basement	Boiler room	WT-042916-4535- A	1.8	WT-042916-4535- B	1.8				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004519	Cooler	Basement	Cafeteria adjacent to entrance	WT-042916-4536- A	< 1	WT-042916-4536- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004520	Cooler	Basement	Cafeteria opposite entrance	WT-042916-4537- A	3.4	WT-042916-4537- B	1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004521	Cooler	1	Adjacent to main office 101	WT-042916-4538- A	< 1	WT-042916-4538- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004522	Cooler	2	2nd floor hallway adjacent to teachers lounge	WT-042916-4539- A	< 1	WT-042916-4539- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004523	Cooler	2	2nd floor across from Stairs	WT-042916-4540- A	< 1	WT-042916-4540- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004524	Cooler	1	First floor hallway adjacent to office 109	WT-042916-4541- A	< 1	WT-042916-4541- B	2.1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004525	Cooler	1	First floor hallway adjacent to ECE boys room	WT-042916-4542- A	< 1	WT-042916-4542- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004526	Cooler	2	2nd floor hallway adjacent room 201	WT-042916-4543- A	< 1	WT-042916-4543- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 004527	Cooler	2	2nd floor adjacent to floor 203	WT-042916-4544- A	< 1	WT-042916-4544- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008606	Classroom	Basement	In art room	WT-042916-8623- A	2	WT-042916-8623- B	1.4				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008607	Kitchen	Basement	In kitchen Left	WT-042916-8624- A	< 1	WT-042916-8624- B	1.1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008608	Kitchen	Basement	In kitchen Right	WT-042916-8625- A	1.1	WT-042916-8625- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008609	Kitchen	Basement	In kitchen spray nozzle	WT-042916-8626- A	160	WT-042916-8626- B	17.3	Filter will be installed and then retested			
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008610	Cooler	1	In hallway adjacent to room 104	WT-042916-8627- A	1.2	WT-042916-8627- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008611	Cooler	1	In health suit room 107 Left	WT-042916-8628- A	< 1	WT-042916-8628- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008612	Classroom	1	In health suit room 107 Right	WT-042916-8629- A	< 1	WT-042916-8629- B	1.3				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008613	Break Room	1	In room 109	WT-042916-8630- A	1.9	WT-042916-8630- B	2.6				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008614	Cooler	1	In classroom 110	WT-042916-8631- A	1.6	WT-042916-8631- B	< 1				
GARFIELD ELEMENTARY SCHOOL	5/11/2016	WS- 008615	Cooler	1	In classroom 111	WT-042916-8632- A	< 1	WT-042916-8632- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.